

# FIELD INSPECTION REPORT

Date of Inspection:	27-1-2021	District: Kishanganj
Division: Kishanganj-1		Length(km): 0.300
Name of the Road:	Loza road to Khurkhuriya tola.	
Scheme/Programme:	GTSNY.	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed /Under Maintenance ~	
Work is a case of:	New Connectivity/ Up gradation / Maintenance ~	
S1. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	~S/U
a)	Road Junction Condition	~S/U
b)	Condition of Surfacing	~S/U
c)	Riding Quality	~S/U
d)	Road Camber	~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	~Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	~Yes/No
g)	Compaction of flank / shop & raincuts if any	~Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	~S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	~S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	~S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	~Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	no ATR

Overall Rating :

Satisfactory(S)	" S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Sanjeev Kumar Paswan  
27/1/2021  
(Signature)

NAME: Sanjeev Kumar Paswan  
J.E, RWD, Terhagachh