

FIELD INSPECTION REPORT

Date of Inspection	8.1.21	Location	Just chauras
Inspector	Manish Kumar	Length (km)	1.40 km
Name of the Road	Bulandshahr to Jhansi Rd		
Schematic Programme	MSDP/2017-2021		
Package No.	Road Id No.		
Status of the Project	☒ New / ☒ Improved / ☐ Rehabilitation / ☐ Maintenance		
Work in a year of:	☒ 1st / ☒ 2nd / ☐ 3rd / ☐ 4th / ☐ 5th		

Sl. No. Parameters to be checked Remarks

1.	Pavement	
a)	Road function condition	✓
b)	Condition of Surfacing	✓
c)	Binding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as surface cracks, exposed aggregates in case of CC Pavement	Yes/✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/✓
g)	Compaction of hardslope & raincuts if any	Yes/✓

2. Cross Drainage

a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI/✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SRI/✓
c)	Condition of railings/slabs/approach for Bridges	✓SRI/✓

3. Road Furniture

a)	Whether sign boards/informatory/cautionary Board/km & 100m stone/Pavement road markings are provided and maintained	Yes/✓
----	---	-------

4. Compliance History

a)	Status of ATR's & any others	No
----	------------------------------	----

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
16/1/21

NAME: Manish Kumar

Shot on Y12
Vivo AI camera