

GTSNY
FIELD INSPECTION REPORT

Date of Inspection : 22.1.21	District: Aurangabad
Division : Aurangabad	Length (km): 1.10 Km
Name of the Road: Deo Amba Road to Ughora.	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road surface condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Condition of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SI/U
c)	Condition of railings slab approach for Bridges	S/SI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stone. Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of AIR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

NAME: Dina Neth R

Dina
22/1/2021
(Signature) J.E