

**GGSNY**  
**FIELD INSPECTION REPORT**

|                                                               |                      |
|---------------------------------------------------------------|----------------------|
| Date of Inspection : 22.1.21                                  | District: Aurangabad |
| Division : Aurangabad                                         | Length (km): 1.00 Km |
| Name of the Road: Coping Bigla to Bharath.                    |                      |
| Scheme/Programme: MAINTENANCE                                 |                      |
| Package No.:                                                  | Road Id No.:         |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                      |

| Sl. No. | Parameters to be checked                                                                                             | Remarks                                                    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                                                            |
| a)      | Overall condition                                                                                                    | S                                                          |
| b)      | Condition of Surfacing                                                                                               | S                                                          |
| c)      | Riding Quality                                                                                                       | S                                                          |
| d)      | Road Camber                                                                                                          | S                                                          |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No                                                     |
| f)      | Construction Joints provided or not (CC Pavement)                                                                    | Yes/No                                                     |
| g)      | Condition of bankslope & raincuts if any                                                                             |                                                            |
| 2.      | <b>Cross Drainage</b>                                                                                                |                                                            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U                                                    |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U                                                    |
| c)      | Condition of railings slab approach for Bridges                                                                      | S/SRI/U                                                    |
| 3.      | <b>Road Furniture</b>                                                                                                |                                                            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 100m stages Pavement road markings are provided and maintained | Yes/No                                                     |
| 4.      | <b>Compliance History</b>                                                                                            | Maintenance Board not found.                               |
| a)      | Status of AIR's & any others                                                                                         | No plan in filling in flange,<br>No road furniture in road |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

**SRI**

*[Signature]*  
22.1.21

AE, Kutchra

NAME: