

GTSNY
FIELD INSPECTION REPORT

Date of Inspection : 22.1.21		District: Aurangabad	
Division : Aurangabad		Length (km): 1.55 Km	
Name of the Road: Bighu Bighu to Baheta Road.			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Surface condition	S	S/U
b)	Condition of Surfacing	S	
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Condition of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings slab approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 100m stones Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Maintenance Board not found, Bushes found in both side of flanks
Road Signage not found.

Overall Rating : Satisfactory (S)
Satisfactory but requires Improvement (SRI) **SRI**
Unsatisfactory (U)

[Signature]
22.1.21
AE, Kurlumbga

NAME: