

FIELD INSPECTION REPORT

Date of Inspection : 12-01-2021	District: GAYA
Division : SHERGHATI	Length (km): 1.931
Name of the Road: LO21 TO BIGHA PAR (NANADIH)	
Scheme/Programme: MAINTENANCE	MMGSY
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	N-A
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N-A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N-A
g)	Compaction of flank/slope & raincuts if any	Yes/No N-A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

The Road in question is in "on-going" stage. The WBH (Gr-III) has been completed & the PMC is yet to be done.

(Signature) *Balraj*
12.01.21

NAME: *Balraj Kishore Prasad*
DESIGNATION: *Assistant Engr/ Sobhi*