

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Samsi HPur</u>
Division : <u>RWD Raserg</u>		Length (km): <u>1.020</u>
Name of the Road: <u>L034 - Tola to Yadav tala Marthua</u>		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
16/01/2021
(Signature)

NAME: Ravi Prasad Paswan
DESIGNATION: J.E. M.H.