

26

S4

3L

28

## Inspection Report For Flood Damage Work

Date :

1 Name of PIUs : Gopalgarh-2

2 Name of Block/Road : Baikunthpur / Jagdishpur Mod Pitha Sadak TO Munja  
Baunihar TOL

### A For Road

1 Damage Location / Chainage : 50m to 385m

2 Damage Length : 63m

3 Nature of Damage : Heavy Rain / Flood

4 Details of Restoration Works:

i. Material being used in Restoration Works: Brick Bats

ii Equipments / Tools being used in Restoration Works: JCB, Tractor, Prol, shovel, Beldy

iii Procedure taken up in Restoration Works: Yes

iv Restored Length: 63m

### B For Bridge

N/A

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restoration Works:


i. Material being used in Restoration Works :


ii Equipments / Tools being used in Restoration Works :


iii Procedure taken up in Restoration Works:

iv Restored Length :

  
25/9/2020  
JE

  
25.09.2020  
AE

  
25/9/20  
EE

  
25/9/21  
Signature  
Executive Engineer  
(Name of Inspector)  
R.W.D. W.D.  
Hathua



बिहार सरकार

# ग्रामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

## FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR  
DISTRICT :- GOPALGANJ  
BLOCK :- BAIKUNTHPUR

Jaadishpur Mod Pitch Sadak To Munja Bhumihar Tola

ESTIMATED COST - RS.

465000.00

SUBMITTED BY :-  
EXECUTIVE ENGINEER  
RWD (W) DIVISION  
GOPALGANJ-2

## Report

Name of Work :- Motorable work of Jagdishpur Mod Pitch Sadak  
To Munja Bhumihaar Tola

Estimated Cost :- 465000.00


Total length of Road :- 0.979 km


Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

  
19/9/2020  
J.E.

  
19.09.2020  
A.E.

  
19/9/20  
E.E.

**Detailed Estimate For Motorable Work in Road from Jagdishpur Mod Pitch Sadak To Munja Bhumihar Tola damaged due to Heavy rain/flood for year 2020-2021**

Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all complete job.								
CH - 50 M to 385 M	1	6.00	4.05	0.18	4.37	M3		
	1	1.00	2.00	2.50	5.00	M3		
	1	9.50	1.20	1.80	20.52	M3		
	1	1.50	2.00	2.40	7.20			
	1	24.00	2.20	1.55	81.84	M3		
	1	18.00	1.90	0.84	28.73	M3		
	1	3.00	3.50	4.00	42.00	M3		
Less for H.P.	0	0.00	0.00	0.00	0.00	M3		
					189.66		2442.11 2427.65	457481.24 460432.95
Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2.50			0.00	M	2744.50 4159.56	0.00
								457481.24 460432.95
Add 1 % Contingency								4575.50 4604.33
							Total	462056.24 465037.28
							Say	465000.00

*[Signature]*  
19/9/2020  
J.E.

*[Signature]*  
19.09.2020  
A.E.

*[Signature]*  
19/9/20  
E.E. Rs. 462056.24  
Say Rs 4.62 lacs.

Technically Approved For Rs 4.621 lac (Rupees Four lac Sixty Two Thousand & One Hundred) only

*[Signature]*  
21/10/21  
Superintending Engineer  
RWD Works Circle, Siwar  
21/10/21  
u