

3L 18 3
Inspection Report for Flood Damage Work

Date:

1. Name of PIUs RWD, works Division, Gopalganj - 2
2. Name of Block/Road - Sidhwalia / Salehpur PMGSY Sadak Ramkrishna Sharma ke Khar pas to Rampurwa tola bandh Tola

A. For Road

1. Damage Location/Chainage : 12.00M | 17.00M
2. Damage Length : 16.00M | 21.60M
3. Nature of Damage : Road partially washed out
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works: JCB, Tractor & Trolley
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 37.60M

B. For Bridge


1. Damage Location/Chainage : | NA
2. Damage Length : | NA
3. Nature of Damage : | NA
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works: | NA
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length



JE



AE


18/9/20

EE


4/10/21

Signature
Executive Engineer
(Name of Inspector)
Hathua



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

FLOOD DAMAGED REPAIR (F.D.R)

STATE :- BIHAR
DISTRICT :- GOPALGANJ
BLOCK :- SIDHWALIA

Jhajhwa - Salehpur PMGSY Sadak Ramkrishna Sharma Keb
Ghar peas to Rampurwa Tola bandh Tola

ESTIMATED COST RS 335400.00

SUBMITTED BY:
EXECUTIVE ENGINEER
RWD (W) DIVISION -
GOPALGANJ-2

Report.

Name of work :- Jhajhwa -Salehpur PMGSY Sadak Ramkrishna
Sharma Keb Ghar peas to Rampurwa tola
Band tola


Estimated Cost :- Rs 335400.00


Total length of road :- 2.50 KM


Description :- The present estimate has been framed under the supervision of Assistant engineer in accordance with the order of Executive Engineer , RWD , WD Gopalganj-2 , letter no – 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transportation has been obstructed . The immediate motorable work is necessary in public interest . Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats .

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.


18-09-20
J.E.



18/9/20
A.E.



18/9/20
E.E.


Detailed Estimate For Motorable Work in road Jhajhwa - Salehpur PMGSY Sadak
Ramkrishna Sharma Keb Ghar peas to Rampurwa tola Bandh Tola damaged due to
Heavy rain / Flood for Year . 2020-2021

Sr.	Items	no.	L (M.)	W M.)	D (M.)	Qty.	unit	rate	Amount
1	Providing brick bats billed in ditches including all cost of Labour & Material with all complete job .								
	CH- 1200 M to 1300 M	2	8.00	2.00	0.30.	9.60	M ³		
	CH - 1700 M to CH - 1900 M	2	7.50	5.00	1.50	112.50	M ³		
		1	3.40	1.00	1.50	5.10	M ³		
		1	3.20	2.00	1.50	9.60	M ³	2412.11	329977.20
						136.80	M ³	2427.65	332,102.52
									332102.52
	Add 1% contingency							3355.26	3321.03
							Total		335423.55
							Say		335400.00


Rs 335277.20
Say Rs 3.35 L


18-09-20
JE


18/9/20
AE


18/9/20
EE

Technically Approved for Rs 3.355 Lacs (Rupees) Three Lacs.
(thirty Three Thousand & Three Hundred) only


21/01/21
Superintending Engineer
RWD Works Circle, Siwan
21/01/2021