# Inspection Report For Flood Damage Work

Date:

1 Name of PIUs: Gofsel gary - 2

2 Name of Block/Road: Beilcenthow / Progsy Pera to vikram Singh Kelolg

#### A For Road

1 Damage Location / Chainage: 210 m to 790 m

2 Damage Length: 227.0-0 0

3 Nature of Damage: Heavy Rain / Plood.

4 Details of Restroration Works:

i. Material being used in Restoration Works:

Brick Bals

ii Equipments / Tools being used in Restoration Works: IcB, Tactor, Tool, Belchy, Shawel.

iii Procedure taken up in Restoration Works:

iv Restored Length:

227.000

B For Bridge

NIA

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
  - i. Material being used in Restoration Works:
  - ii Equipments / Tools being used in Restoration Works:
  - iii Procedure taken up in Restoration Works:

iv Restored Length:

Phy 11112020

24.11.2020

FF

Execusionation (NaRiante)

Hathua





# ग्रामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

# FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

PMGSY Path To Vikram Singh Ke Tola

ESTIMATED COST - RS.

-1402000.00 1255 300 200

SUBMITTED BY :-EXECUTIVE ENGINEER RWD (W) DIVISION GOPALGANJ-2

### Report

Name of Work

:- Motorable work of PMGSY Path To Vikram

Singh Ke Tola

**Estimated Cost** 

:- 1402000.00 (255300=00

**Total length of Road** 

:- 1.720 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road. Hence there has been a provision of laying 2 Nos of R.C.C. NP3 1000 MM Dia hume pipe.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

J.E.

A.F.

FF

## Detailed Estimate For Motorable Work in Road from PMGSY Path To Vikram Singh Ke Tola damaged due to Heavy rain/flood for year 2020-2021

r. Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all complete job.								
CH - 210 M to 290 M	1	28.00	1.20	0.50	16.80	МЗ		
	1	14.00	1.50	0.60	12.60	M3		
	1	16.00	3.00	1.60	76.80			
	1	12.00	1.10	1.05	13.86			
	1	26.00	2.50	2.30	149.50			
	1	29.00	1.70	1.90	93.67			
	1	30.00	2.30	1.00	<del>- 69.0</del> 0			
	1	15.00	1.40	1.20	25.20			
	1	10.00	1.20	0.60	7.20			
	1	-19.00	<del>-2.50</del>	0.90	20./6 +42.75			
	1	<del>26.0</del> 0	1.20	1.20	37.44			
	1	30.00	0.90	1.00	18.90 -27.00			
Less for H.P.	0	1.23	1.23	0.95	0.00	М3	2412-11	123492820
					<del>-571.8</del> 2		2427.65	<del>1388178.8</del> 2
Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2.50			51197 0.00	М	274450 4159.56	1 <del>242883</del> •97 0.00
								-1388178.82
Add 1 % Contigency							1434921	13881.79
							Total	1402060.61
							Say	<u>1402000,0</u> 0

Pe 12 55 300 =00 Pr. 124727726 Sey Rt 12.473 Le.

A.E.

924/11/W

E.E.

Technically Approved for Rs 12.473 lave (Repres Twelve la. Forty Seven Thousand & Three Hundred July

Superintending England
RWD Works Gircle, Sive