

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Vihar*

2 Name of Block/Road :- *Khaneradpur PWD road to Ram Sahay Chhokra*

(A) For Road:

1. Damage Location/Chainage :- *ch 2000, 2300, 2500*
2. Damage Length :- *11.30m*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brown salt.*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *11.30m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

15.12/
Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Khanezadpur PWD Road to Ram Sahay Chhopra

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.727 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.731
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.731
TOTAL COST OF PROJECT IN LACS =		0.731

say 0.73 lac


07.01.2021

JE
RWD




AE
RWD


7/1

EE
RWD

Technically approved for Rs 0.73 lac
(Rupees seventy three thousand only)


SE 12.1.21

RWD work circle
muzaffarpur