

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Vihhar*

2 Name of Block/Road :- *minabur PWD Ganga Chowk to Chaitpur Dharbur*

(A) For Road:

Raghubur pmlsy road.

1. Damage Location/Chainage :- *CH 450, 700, 900, 970, 5280, 5430, 5470,*

2. Damage Length *264.90m* :- *5730, 6230, 6540, 6570, 7155*

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- *Brick ball*

(ii) Equipment's/Tools being used in Restoration works:- *Tractor*

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- *264.90m*

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Minapur PWD Gangli Chowk to Chainpur Dharpur Raghonpur PMGSY Road

Muzaffarpur

District

Minapur

Block

Muzaffarpur East-2


Division


8.431 Km

Length of Road (in Km)

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	30.339
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	30.339
TOTAL COST OF PROJECT IN LACS =		30.339


Say 30.34 lac


JE
07.01.2021
RWD


AE
RWD


EE
21/1
RWD

Technically approved for Rs 30.34 lac
(Rupees Thirty four thousand only)


SE
RWD name circle
muzaffarpur