

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Uyan villagar*

2 Name of Block/Road :- *Urnam Koli ke gandhi Nagar to yogendra Ram ke ghar*

### (A) For Road:

1. Damage Location/Chainage - *6294, 155, 370, 500 etc at many places*
2. Damage Length :- *246.40m*
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- *Brick bats*
  - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- *246.40m*

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

*[Signature]*  
Signature

(Name of Inspection)  
**Executive Engineer**  
**R.W.D. Works Division**  
**Muzaffarpur East-1**

### GENERAL ABSTRACT

Name of Road Gram Koili Ke Gandhi Nagar to Yogendra Ram Ke Ghar

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km)


1.016 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	14.154
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	14.154
TOTAL COST OF PROJECT IN LACS =		14.154


say 14.15 lac

  
27/01/2021

JE  
RWD



AE  
RWD

  
EE

RWD

Technically approved for Rs 14.15 lac  
(Rupees fourteen lac fifteen thousand only)

  
SE

RWD zone circle  
muzaffarpur