

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Vishwak*

2 Name of Block/Road :- *Near Chandehwar Chas to Vi Jay Ram*

(A) For Road:

1. Damage Location/Chainage :- *ch 135^m to 200^m*
2. Damage Length :- *66.10^m*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Briquet*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *66.10^m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Near Chandeswar Ghar to Vijay Ram
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 0.400 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1 | Jhama metal | 2.149 |
| 2 | Sand Filling | 0.000 |
| 3 | Sand bag | 0.000 |
| 4 | H.P. | 0.000 |
| | GRAND SUB TOTAL | 2.149 |
| TOTAL COST OF PROJECT IN LACS = | | 2.149 |


say 2.15 lac


07.01.2021

JE
RWD



AE
RWD


EE
RWD

Technically approved for Rs 2.15 lac
(Rupees Two lac fifteen thousand only)


16.1.21
SE

RWD work circle
muzaffarpur