

FIELD INSPECTION REPORT

Date of Inspection: 21-1-2021		District: Kishanganj
Division: Kishanganj-1		Length(km): 0.800
Name of the Road: To 2 PMWSY road to gari tola.		
Scheme/Programme: GTSNY.		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed /Under Maintenance ✓
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓
S1. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank / shop & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	16/ ATR.

Overall Rating :

Satisfactory(S)	" S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh

Sanj
21/1/2021
(Signature)