

FIELD INSPECTION REPORT

Date of Inspection :	10/1/20	District:	Siwan
Division :	Deharajganj	Length (km):	2.00 km
Name of the Road:	704 to Jafalpur		
Scheme/Programme:	MAINTENANCE	/ PMGSY	
Package No.:	BR-342-303	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement D.T.	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing Some part AT. damaged for heavy vehicle & heavy pump.	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	None

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Ravi Sagar Das

NAME:

DESIGNATION: J-E

10/1/20
(Signature)