FIELD INSPECTION REPORT

Date of Inspection: Division: Jayragan			District: Madhybani Length (km): p.410 k	
Name	of the Road: Do	AKhinwari Tola-H	0.410 Km	
	e/Programme:	MAINTENANCE	GITSNY	
Package No.: Status of the Project: Work is a case of:		Road Id No.: Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
1.	Pavement		A SAME	Remarks
a)	Road Junction condition			SAU
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
1	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitur	e i		
a) :	Whether sign stones/Pavemen	boards/informatory/c tt road markings are p	autionary Board/km & 200m orovided and maintained	Yes/No

Overall Rating

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Chiloanjan Rahul

Compliance History

Status of ATR's & any others

DESIGNATION: JE