Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan vibhalcar

2 Name of Block/Road: - Aurai | Pintoihiya HH-57 to Primary mmusy (sc)
(A) For Road: School to Bhikhari Singh house.

1. Damage Location/Chainage :- Octoo 1cm, octoo 1cm

2. Damage Length :- 0.02896 Km

3. Nature of Damage :-4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick bate

(ii) Equipment's/Tools being used in Restoration works:- Trackers

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 0.02896 Km

(B) For Bridge:

- 1. Damage Location/Chainage :-
- 2. Damage Length :
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल,मुजनफरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Pintojhiya NH-57 to Primary MMGSY (sc) School To Bikhari Singh House

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

0.380 Km

SCRIPTION hwork	0.000 2.515
	2.515
ma metal	0.000
d Filling	0.000
d bag	0.000
	2.515
ND SUB TOTAL	2.515
d	Filling bag

RWD

Technically approved for RS 2-515 lac (Rupees two lac staty one shousand five hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर