



### GENERAL ABSTRACT

me of Road Kamrathu Jarang Road me Krishna dco Singh House to Mushar Tola Sakwara Savik  
istrict Muzaffarpur  
ock Gaighat  
ision Muzaffarpur East-2  
ngth of Road (in Km) 1.520 Km


No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.076
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	5.076
TOTAL COST OF PROJECT IN LACS =		5.076

  
JE  
RWD

  
AE  
RWD

  
EE  
RWD

Technically approved for RS 5.076 lac  
(Rupees five lac seven thousand six hundred only)

  
अधीक्षक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अंचल, मुजफ्फरपुर

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE, RWD Murallaipur East-2

2 Name of Block/Road :- Gaighat / Karamchhi Jangal road on Karmachhi  
Sinh House to another side Saharajung Sarda

### (A) For Road:


1. Damage Location/Chainage :- At many places
2. Damage Length :- 0.4514 km
3. Nature of Damage :- Complete traffic blocked due to flood damage by flood waters
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Jhera, gravel
  - (ii) Equipment's/Tools being used in Restoration works:- JCB, Pallet, Roller
  - (iii) Procedure taken up in Restoration works:- Immediate restoration of traffic
  - (iv) Restored Length :- 0.4514 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

N/A

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EE  
RWD Work Division  
Murallaipur East-1