Inspection Report for Flood Damage Work

Date:-

- 1 Name of PIUs: Gyan vi blakar
- 2 Name of Block/Road: howe of uncer vai to house of Bighan Perm

(A) For Road:

- 1. Damage Location/Chainage :- 0.050 km, 0.070 km, 0.085 km
- 2. Damage Length :- 0.0275 km

(Legn = 0.100 kg)

- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:- back bat
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- 0.0275 km

(B) For Bridge: ×

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature 2

(Name of Inspection)

EE

RWD WOOK DIVISION

MY29/Jux bus East-L

GENERAL ABSTRACT

Name of Road

House of Umes Rai to House of Bighan Ram

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

0.100 Km

		AMOUNT (LAKHS)	
SI. No.	DESCRIPTION	The state of the s	
1	Jhama metal	1 770	
2	Sand Filling	0.000	
3	Sand bag	0.000	
4	H.P.	173	
	GRAND SUB TOTAL	1 720	
TOTAL (COST OF PROJECT IN LACS =	1,720	

(AR 31/14/200

JE RWD 4-1/2/20

AE

RWD

an []

EE

OWB

Technically approved for RS 1-72 lac (Rupees one lac seventy two thousand only)

> अधीक्षण अणियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरहुर