

GENERAL ABSTRACT

Name of Road Chand Kishor ji Mukhiya Ghar to Marwa Siman
District Muzaffarpur
Block Gaighat
Division Muzaffarpur East-2
Length of Road (in Km) 2.141 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.530
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	8.530
TOTAL COST OF PROJECT IN LACS =		8.530

[Signature]
JE
RWD

[Signature]
AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 8.53 lac
(Eight lac fifty three thousand only)

[Signature]
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE/RWD Muradpur East-2
2 Name of Block/Road :- Gaighat/Chand Kishor J Mukhiya Gharto
Merga Simon.

(A) For Road:


1. Damage Location/Chainage :- At many places
2. Damage Length :- 0.3214 km
3. Nature of Damage :- Complete traffic blocked due to road damaged by flood water
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Potholes at Jhama road
 - (ii) Equipment's/Tools being used in Restoration works:- JCB, Tractor, Roller
 - (iii) Procedure taken up in Restoration works:- Immediate restoration of traffic
 - (iv) Restored Length :- 0.3214

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

N/A

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD works Division
Muradpur East-1