

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Jamala J.P. Chowk to Nawada
 Hazards: Flood/Rain
 Division: Muzaffarpur-1 District: Muzaffarpur Actual Length (in km): 1.600KM
 Damage Length (in km): 0.400 KM Damages Location/Chainage: 0.500KM To 0.900KM

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

YES(S)

Description of observation :

c)

Quality of Construction Material Used

Good(S)

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

—

Description of observation :

e)

Compaction of flanks/ slope & raincuts

In progress

Description of observation :

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

NA

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: Ram Kumar Mishra

Designation: E.E., R. Lab Gulzarbag, Patna

01.07.2021

(Signature)