

(Signature)

INSPECTI	ON REPORT FOR FLOOD /RAIN DAMAGE	ROAD
Name of Scheme: NH- 5	TO TELLYA POKHAR.	
Hazards	Flood/Rain	
Division: DARBHANGA-		
Damage Length (in km): 0	450km Damages Location/Chainage: 0 to 4	50 Metre
Name of Scheme/Programme		
Status of Project:	Under Agreement/Out of Agreement	,
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S'
Description of observation:	cc surpcing found in good Cond	2 4 cm
b)	Adequate Thickness of pavement layers constructed	5'
Description of observation :	Adequate thickness found.	
c)	Quality of Construction Material Used	S'
Description of observation :	Good Quality Material used	
<b>d</b> )	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	5
Description of observation :	Found in good Carclition.	
e)	Compaction of flanks/ slope & raincuts	
Description of observation :	Flank work not done, in Progra	) ·
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of vein Creatance  Condition of railings/Slab/approach for Bridges	
,		
Description of observation of C	D WORKS: O Protection wall work	
CD,	Dworks: work and protection wall work clone due to water logging '	
temark if any:	Dionic D	
Overall Rating		
Croimi Naming		(c)
	Satisfactory (S) / Unsatisfactory (U)	(5)
Name of Officer: CHANO	RA SHEKHAR AZAD	021714

E.E.

Designation: