

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Lozakhhabana to Sanjanpur Tar</u>			
Hazards	Flood/Rain	<u>Flood</u>	
Division: <u>Benipur</u>	District: <u>Darbhanga</u>	Actual Length (in km):	<u>3.654</u>
Damage Length (in km): <u>0-200</u>	Damages Location/Chainage: <u>550m</u>		
Name of Scheme/Programme: <u>Ro FDR 3054</u>			
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC) <u>C.C.</u>		<u>S</u>
a)	Condition of Surfacing		
Description of observation :			

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>GSB grading - I 100mm</u> <u>WBM gr-III 75mm</u> <u>P-C.C. 160mm</u> <u>335mm</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation :		

e)	Compaction of flanks/ slope & raincuts	<u>U</u>
Description of observation : <u>Earth work not done</u>		

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>S</u>
b)	Condition of Vent Clearance	<u>S</u>
c)	Condition of railings/Slab approach for Bridges	<u>NA</u>
Description of observation of CD works :		

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer

Bindu Rajal
Executive Engineer
W.D. Regional Laboratory Darbhanga

Designation

[Signature]
07/07/21
A.E.

(Sign)

[Signature]
07/07/21