

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Benipuri Mishra House to Mahinam Chhat.</u>		
Hazards	Flood/Rain - <u>Flood</u>	
Division: <u>Benipur</u>	District: <u>Darbhanga</u>	Actual Length (in km): <u>0.650</u>
Damage Length (in km): <u>0.650</u>	Damages Location Chainage: <u>0 to 650m</u>	
Name of Scheme/Programme: <u>FDR 3054</u> ✓		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>	<u>S</u>
a)	Condition of Surfacing	

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>M.S.S. - 20mm</u>		

c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>NA</u>
Description of observation :		

e)	Compaction of flanks/ slope & raincuts	<u>S</u>
Description of observation :		

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N.N</u>
b)	Condition of Vent Clearance	<u>N.N</u>
c)	Condition of railings/Slab/approach for Bridges	<u>N.N</u>

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Bindu Rajan  
**Executive Engineer**  
 Designation: **RWD, Regional Laboratory**  
**Darbhanga**

[Signature]  
02/07/24  
A.E.

[Signature]  
02/07/24  
 (Sign)