

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Dhaka Wherasahi Road Disratiya to Pipra</u>		
Hazards	<u>Flood/Rain</u>	
Division: <u>Dhaka</u>	District: <u>East Champaran</u>	Actual Length (in km): <u>1.200 km</u>
Damage Length (in km): <u>0.115 km</u>	Damages Location/Chainage:	
Name of Scheme/Programme:	<u>Restoration</u>	
Status of Project:	<u>Under Agreement/Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>—</u>
Description of observation :		
<u>B-T Work not done.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>—</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
<u>ISM WBM-II Work done.</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	<u>—</u>
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>—</u>
b)	Condition of Vent Clearance	<u>—</u>
c)	Condition of railings/Slat/Approach for Bridges	<u>—</u>
Description of observation of CD works :		
<u>—</u>		
Remark if any:		
<u>Only ISM WBM-II done. But other damage length not Work done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>U</u>
---------------------------------------	----------

Name of Officer: Sri Kant Prasad

Designation: E.E.

22/01/21

21/1/2021
(Signature)