

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Bargaon chowk to Athar Road</u>		
Hazards		Flood/Rain
Division: <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>0.800</u>
Damage Length (in km): <u>0.082</u>	+ Damages Location/Chainage: <u>455.00 - 485.00M, 570.00 - 600.00M & 650.00 - 672.00</u>	
Name of Scheme/Programme:		
Status of Project:		
Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	U
Description of observation : <u>Permanent Restoration work not done in damages Location</u>		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Permanent Restoration work not done in damages Location</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer: Ram Kumar Mishra

Designation: EE. R. Lab, Gulzarbag, Patna

S2
02-07-2021

(Signature)