

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>L046-T08 to Dharhar</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Kishanganj-1</u>	District: <u>Kishanganj</u>	Actual Length (in km): <u>7.250</u>
Damage Length (in km): <u>0.350</u>	Damages Location/Chainage: <u>3.17, 6.10, 3.67, 4.2</u>	
Name of Scheme/Programme: <u>FDR</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) <u>BT</u>	<u>S</u>
a)	Condition of Surfacing	
Description of observation: <u>Good Condition</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation: <u>MSS - 20mm thickness</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation: <u>Good</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation: <u>No Defect</u>		
e)	Compaction of flanks/ slope & raincuts	<u>S</u>
Description of observation: <u>At few places, raincut developed, Needs to be repaired.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works: <u>No Provision in this Estimate</u>		
Remark if any: <u>At 2.6751km chainage Due to flood water, About 60m length of Road is water logged.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Satisfactory (S)</u>
---------------------------------------	-------------------------

Name of Officer:

Designation:

Maresh Pd Gupta
EE, RWP Regional Lab.
Purnea

03/07/2024
 (Signature)