

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Dhaka Unhasalon to Tinkauliya</u>		
Hazards		Flood/Rain
Division: <u>Dhaka</u>	District: <u>East Champaran</u>	Actual Length (in km): <u>2.853 km</u>
Damage Length (in km): <u>0.056 km</u>	Damages Location/Chainage:	
Name of Scheme/Programme:		<u>Restoration</u>
Status of Project:		Under Agreement/Out of Agreement
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
—		
Remark if any:		
<u>Permanent Restoration not work done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	U
---------------------------------------	---

Sri Kant Prasad

Name of Officer

Designation: E-E

Ex
02/07/24

293
24/7/24
(Signature)

Scanned By Scanner Go