

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Jhannam Kundwa Champu Road to Gishani via Jafwallya

Hazards: Flood/Rain

Division: Dhaka District: Lalmonirhat Actual Length (in km): 5.250 km

Damage Length (in km) 0.100 km Damages Location/Chainage:

Name of Scheme/Programme: Restoration

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1	Pavement (BT/CC)	
a)	Condition of Surfacing	—

Description of observation: BT work not done.

b)	Adequate Thickness of pavement layers constructed	—
----	---	---

Description of observation: 22M WBM-III work done

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation: 22M WBM-III work done.

d)	Whether free from any defects and irregularity example: Surface Cracks, Undulations, exposed aggregates in case of CC Pavements, Poor workmanship, etc.	—
----	---	---

Description of observation:

e)	Compaction of flanks/slope & raincuts	—
----	---------------------------------------	---

Description of observation:

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—

Description of observation of CD works: —

Remark if any: only 22M WBM-III done. But other damage length not work done.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kank Prasad

Name of Officer

Designation: G.E

Signature

(Signature)

Scanned By Scanner Go