

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Lo31-T01 to Lagma Harnjan Tola</u>		
Hazards	Flood/Rain <u>Flood</u>	
Division: <u>Benipur</u>	District: <u>Darbhanga</u>	Actual Length (in km): <u>2.90</u>
Damage Length (in km): <u>0.510</u>	Damages Location/Chainage: <u>800m to 1310m</u>	
Name of Scheme/Programme:	<u>FDR-30.54</u> ✓	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>CC</u>	<u>S</u>
a)	Condition of Surfacing	

Description of observation : At chainage 800m to Length - 350m
P.C.C. work done.

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>G.S.B Gr I - 100mm</u> <u>W.B.M Gr III - 75mm</u> <u>P.C.C - 100mm</u> <u>335mm</u>		
c)	Quality of Construction Material Used	<u>S</u>

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
----	---	----------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>Both side of the ^{road} there is built up</u> <u>Area, so earth work not done in flank</u>		

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N.A</u>
b)	Condition of Vent Clearance	<u>N.A</u>
c)	Condition of railings/Slab/approach for Bridges	<u>N.A</u>

Description of observation of CD works :

Remark if any: Rest Length of P.C.C 160m W.B.M Gr III in
Progress

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Bindu Rajal
Executive Engineer
Designation: RWD, Regional Laboratory
Darbhanga

03/07/24
A.E.

03/07/24
(Signature)