

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: <u>Bihar Sahen Bakuliya Road Nahar Chowk to Paraniya Warden</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Dhaka</u>	District: <u>East Champaran</u>	Actual Length (in km): <u>1.480 km</u>
Damage Length (in km): <u>0.390 km</u>	Damages Location/Chainage:	
Name of Scheme/Programme: <u>Restoration</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation:		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation:		
c)	Quality of Construction Material Used	—
Description of observation:		
d)	Whether free from any defects and Irregularity example: Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	—
Description of observation:		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation:		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works:		
Remark if any: <u>Permanent Restoration work not done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

3/3
3/3/2021
Name of Officer
Sri Kant Prasad
Designation: P.E.

E.Y.
03/03/21
AC

3/3
3/3/2021
(Signature)