

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD		
Name of Scheme: <u>Mishrauliya to Pakasiya</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Dhaka</u>	District: <u>East Champaran</u>	Actual Length (in km): <u>9.325 km</u>
Damage Length (in km): <u>0.420 km</u>	Damages Location/Chainage:	
Name of Scheme/Programme: <u>Restoration</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks (S/U)
1	Pavement (RT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any:		
<u>Permanent Restoration work not done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>U</u>
---------------------------------------	----------

Sri Kant Prasad.

Name of Officer

Designation: E.E.

03/07/21

03/07/21
(Signature)