

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Di Pahi to Madhavr Road</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Dhaka</u>	District: <u>East Champaran</u>	Actual Length (in km): <u>2.00 km</u>
Damage Length (in km): <u>0.470 km</u>	Damages Location/Chainage: <u>—</u>	
Name of Scheme/Programme: <u>Restoration</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>—</u>
Description of observation:		
b)	Adequate Thickness of pavement layers constructed	<u>—</u>
Description of observation:		
c)	Quality of Construction Material Used	<u>—</u>
Description of observation:		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	<u>—</u>
Description of observation:		
e)	Compaction of flanks/ slope & raincuts	<u>—</u>
Description of observation:		
2	Cross Drainage Structure	
a)	Condition of head walks in Hume pipe culverts	<u>—</u>
b)	Condition of Vent Clearance	<u>—</u>
c)	Condition of railings/Slab/approach for Bridges	<u>—</u>
Description of observation of CD works:		
Remark if any:		
<u>Permanent Restoration Work not done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kant Arond
Name of Officer

Designation: E.E.

Ex
03/07/21

28
03/07/21
(Signature)