

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Chiraiya Chowk to Ahirauliya</u>		
Hazards		<u>Flood/Rain</u>
Division <u>Dhaka</u>	District <u>East Chongra</u>	Actual Length (in km) <u>1.500 km</u>
Damage Length (in km) <u>0.570 km</u>	Damages Location/Chamage:	
Name of Scheme/Programme:		<u>Restoration</u>
Status of Project		<u>Under Agreement/Out of Agreement</u>
Sr. No	Parameters to be Checked in Restoration work	Remarks (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and irregularity example Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
—		
Remark if any:		
<u>Permanent Restoration work not done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kant Prasad.

Name of Officer:

Designation E.E.

Ex
05/07/24
Ac

3/7/24
(Signature)