

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Sakhausa chowk to Sakhausa village</u>		
Hazards	Flood/Rain	
Division: <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>1.180</u>
Damage Length (in km): <u>0.125</u>	Damages Location/Chainage: <u>40.00M-113.00M, 123.00-136.00M, 149.00M-188.00M</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	In progress
Description of observation :		
2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: Ram Kumar Mishra

Designation: E.E. R. Lab, Gulsarbag, Patna

02/07/2021
(Signature)