

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Dilahi to Kali</u>			
Hazards		Flood/Rain	
Division: <u>Darbhanga-1</u>	District: <u>Darbhanga</u>	Actual Length (in km): <u>1.525 km</u>	
Damage Length (in km): <u>1.525 km</u>		Damages Location/Chainage:	
Name of Scheme/Programme: <u>PDR</u>			
Status of Project:		Under Agreement/Out of Agreement <u>Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		<u>S</u>
Description of observation : <u>atent</u> <u>In about 300 M. B.T. done but little broken due to rain.</u> <u>In about 1.225 K.M. B.T. work is not done.</u>			
b)	Adequate Thickness of pavement layers constructed		<u>S</u>
Description of observation : <u>75 mm WBM gr-II done in patches, At few locations further patch is developed due to rain,</u>			
c)	Quality of Construction Material Used		<u>S</u>
Description of observation : <u>Good</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>S</u>
Description of observation : <u>Undulations are existing which should be rectified before B.T. work.</u>			
e)	Compaction of flanks/ slope & raincuts		<u>S</u>
Description of observation : <u>No provision in the scheme</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		<u>S</u>
b)	Condition of Vent Clearance		<u>S</u>
c)	Condition of railings/Slab/approach for Bridges		<u>S</u>
Description of observation of CD works : <u>No provision in the scheme.</u>			
Remark if any: <u>Restoration work completed with WBM gr-3</u> <u>B.T. work in about 1.225 K.M. is to be done.</u>			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Ram prabesh saw

Designation: T.A. RWD
Circle Siway

2/7/21
AE

2.7.21
(Signature)