

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Beheri Bahera Road to Gangdah</u>		Flood/Rain	
Hazards		District: <u>Darbhanga</u>	
Division: <u>Darbhanga-1</u>	Damage Length (in km): <u>0.750 km</u>	Actual Length (in km): <u>0.995 km</u>	
Name of Scheme/Programme: <u>PDR</u>		Damages Location/Chainage:	
Status of Project:		Under Agreement/Out of Agreement <u>Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		
Description of observation : <u>In the DPR, cement concrete pavement in Length 0.750 km is to be done. Work not started</u>			
b)	Adequate Thickness of pavement layers constructed		
Description of observation : <u>No work done</u>			
c)	Quality of Construction Material Used		
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		
Description of observation :			
e)	Compaction of flanks/ slope & raincuts		
Description of observation : <u>No work done</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works : <u>No provision in the scheme</u>			
Remark if any: <u>This road is within village, in which water & Mud is accumulated due to rainy season. No work done.</u>			
Overall Rating			

Satisfactory (S) / Unsatisfactory (U)	<u>U</u>
---------------------------------------	----------

Name of Officer: Ram Prabesh Saw

Designation: TA, RWD
Work Circle Siwan

4.7.21
(Signature)

4/7/21
AC