

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Khagra Top to Basta Dange</u>			
Hazards		Flood/Rain	
Division: <u>Kishanganj 1</u>	District: <u>Kishanganj</u>	Actual Length (in km): <u>4.362 km</u>	
Damage Length (in km): <u>0.120</u>	Damages Location/Chainage:		
Name of Scheme/Programme: <u>FDR</u>			
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks: (S/U)
1.	Pavement (BT/CC) <u>BT</u>		<u>S</u>
a)	Condition of Surfacing		
Description of observation: <u>Good</u>			
b)	Adequate Thickness of pavement layers constructed		<u>S</u>
Description of observation: <u>M.S.S. 20mm Thickers</u>			
c)	Quality of Construction Material Used		<u>S</u>
Description of observation: <u>Satisfactory</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>S</u>
Description of observation: <u>Satisfactory</u>			
e)	Compaction of flanks/ slope & raincuts		
Description of observation: <u>At few places, Rain cut bound.</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works: <u>no provision in this estimate</u>			
Remark if any: <u>At 0-400km chainage, Both side of Road is water logged. As per site condition, 20m span R.C.C. bridge to be needed</u>			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Satisfactory</u>
---------------------------------------	---------------------

Name of Officer: Mahesh Pd Gupta
 Designation: EE, Rwp, Regional Lab
Purnea

04/07/2017
 (Signature)