

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Jhark To Parian Nathama</u>		
Hazards	Flood/Rain	
Division : <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>1.760</u>
Damage Length (in km): <u>0.760</u>	+ Damages Location/Chainage: <u>1.000 TO 1.760 KM</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	U
Description of observation : <u>BT surface damaged at different points in village portion (only 460.00M BT surface has been done)</u>		
b)	Adequate Thickness of pavement layers constructed	U
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	N.A
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Only 460.00 BT Surface has been done & rest 300.00M BT surface was not completed due to water logging in village portion</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	Unsatisfactory
---------------------------------------	----------------

Name of Officer: Ram Kumar Mishra
 Designation: R. Lab., Gulzarbag, Patna


 (Signature) 01/07/2021