

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>L069 Bariyaspur Khand To Gausiher Khalik Nagar</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>1.120</u>
Damage Length (in km): <u>0.330</u>	+ Damages Location/Chainage:	
Name of Scheme/Programme:		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	S
Description of observation : <u>only 77.50 M length in two stretches Permanent Restoration work done in out of 330.00 M ^{damaged} length</u>		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	In progress
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A.
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Only 77.50 M length in two stretches Permanent Restoration work done in out of 330.00 M ^{damaged} length</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab, Gulzargah, Patna

02/07/2021

(Signature)