

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Rampur chowk To Sahpur Maricha</u>		
Hazards	Flood/Rain	
Division : <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>6.40</u>
Damage Length (in km): <u>1.00</u>	Damages Location/Chainage: <u>5.110 KM To 6.110 KM</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement ☒ Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>BT</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>BT Surface damaged at different points in village portion</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	
Description of observation :		
2	Cross Drainage Structure	<u>N.A.</u>
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>BT Surface damaged at different points in village portion.</u>		

Overall Rating

Satisfactory (S) /Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gubbarbag, Palnis

01/07/2021

Signature

01/07/2021