

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Garahia Bazar to Mushar to Garahia Middle School via shekh toli		
Hazards	Flood/Rain	
Division :	District: East	Actual Length (in km): 1.445 km
Damage Length (in km): 0.067 km	Damages Location/Chainage: 0.250 km, 0.350 km	
Name of Scheme/Programme:	FDR (3054)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	
a)	Condition of Surfacing	U
Description of observation : width of BT surface found 3.50m and 3.70 m		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB Gr II - 100 mm WBM Gr III - 75 mm MSS - 20 mm		
c)	Quality of Construction Material Used	S
Description of observation : Good quality material is used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation : N.A.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A.
b)	Condition of Vent Clearance	N.A.
c)	Condition of railings/Slab/approach for Bridges	N.A.
Description of observation of CD works : N.A.		
Remark if any: width of BT surface found 3.50m and 3.70 m.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: Ratnesh Paswan

Designation: E.E.

4/7/21
R.E.

22/7/21
4-7-21
(Signature)
E.E.