

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Ukhara to Niyam</u>		
Hazards	Flood/Rain	
Division: <u>Darbhaug-1</u>	District: <u>Darbhaug</u>	Actual Length (in km): <u>3.0 K.M.</u>
Damage Length (in km): <u>1.60</u>	Damages Location/Chainage: <u>-</u>	
Name of Scheme/Programme:	<u>FDR</u>	
Status of Project:	Under Agreement/Out of Agreement <u>Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>In approx 200 M. B.T. done. In about 1.40 K.M. B.T. work is not done.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>75 mm W.B.M. g-3 done in patches, 20 mm M.C.S. in 200 M length</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good Quality</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>U</u>
Description of observation : <u>Undulations are existing which should be rectified before B.T. work. Ukhara to Niyam distance is 3 km. but estimate is of 1.60 km which is upto Goshari.</u>		
e)	Compaction of flanks/ slope & raincuts	<u>-</u>
Description of observation : <u>No Provision in the scheme</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>-</u>
b)	Condition of Vent Clearance	<u>-</u>
c)	Condition of railings/Slab/approach for Bridges	<u>-</u>
Description of observation of CD works : <u>No Provision in the scheme.</u>		
Remark if any: <u>Restoration work completed with W.B.M. g-3. In about 1.40 K.M. B.T. work is to be done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Ram Phalberh Saw

Designation: T.A. RWD Circle Swam.

2/2/21
AE
(Signature) 2-7-21