

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme:	Tol Narsara Sema to Ram Tola	
Hazards	Flood/Rain	Actual Length (in km): 0.435 km
Division :	District:	
Damage Length (in km):	0.435 km	Damages Location/Chainage: —
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	Out of Agreement
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	
Description of observation : c.c. Pavement thickness - 0.160 m. P.C.C. done in full length.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : c.c thickness - 160 mm		
c)	Quality of Construction Material Used	S
Description of observation : Good.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation : No provision in the scheme		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
C)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works : No provision in the scheme		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

Ram Prabesh Saw

Designation:

T.A, RWD,
Work Circle Siwan.

(Signature)

2.7.21
AE