

## INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: T02 TO SHANKARPUR.		
Hazards	Flood/Rain	
Division : DARBHANGA-2	District: DARBHANGA	Actual Length (in km): 1.60 km.
Damage Length (in km): 0.700 Km.	Damages Location/Chainage:	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) CC	
a)	Condition of Surfacing	
Description of observation : work not yet started		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : work not started		
c)	Quality of Construction Material Used	
Description of observation : work not started		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	
Description of observation : work not started		
e)	Compaction of flanks/ slope & raincuts	
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : NA		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

04/07/21  
A.E.

0417121  
(Signature)