

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Khajauli to Manipaswa Sarathi.</u>		
Hazards		Flood/Rain
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>2.662</u>
Damage Length (in km): <u>0.375</u>	Damages Location/Chainage: <u>Photo attached</u>	
Name of Scheme/Programme: <u>PMUSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>It seemed laying and rolling temp. of MMS not maintained.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>
Description of observation :		
e)	Compaction of flanks/ slope & rain.	
Description of observations: <u>EW in flank not done.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N/A</u>
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>It seemed rolling and laying temp. of mss not maintained.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

21/7/21
RE

(Signature)

02.07.21