

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Sanau to Grandhwal		
Hazards	Flood/Rain		
Division:	Madhubani	District:	Madhubani
Damage Length (in km):	0.665	Actual Length (in km):	4.096
Name of Scheme/Programme:	MMUSP		
Status of Project:	Under Agreement/Out of Agreement		
Damages Location/Chainage:	Photo attached		
Sr. No.	Parameter's to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	S	
a)	Condition of Surfacing	S	

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—

Description of observation :

e)	Compaction of flanks/ slope & rain	S
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N/A
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: Work done found satisfactory

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

3/7/24
4E

(Signature)

03.07.24