

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	To 4 Sarisav to Siswa		
Hazards	Flood/Rain		
Division :	Madhubani	District:	Madhubani
Actual Length (in km):	7.667		
Damage Length (in km):	0.986	Damages Location/Chainage:	Photo attached
Name of Scheme/Programme:	PMGSY		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	S	
a)	Condition of Surfacing	S	

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	-
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & run.	
----	------------------------------------	--

Description of observation:

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N/A
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: None found satisfactory.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

11/7/21
HE

(Signature) 01.07.21