

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Tas Sisaina to Subhankar pur</u>		
Hazards <u>Flood/Rain</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>7.815</u>
Damage Length (in km): <u>0.423</u>	Damages Location/Chainage: <u>Photo attached</u>	
Name of Scheme/Programme: <u>PM USY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>

Description of observation :

e)	Condition of flanks/ slope & rain.	
Description of observation: <u>EW in flank not started.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N/A</u>
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: Road width (Carriage width) found less than 3.75M in some stretches. (3.50M) Av.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

11/7/21
WC

(Signature)

Signature
01.07.21